



MOFFMAY NIGERIA LIMITED

Projects Executed

S/no	PROJECT	SERVICES PROVIDED	CONTRACTOR	CLIENTS	YEAR COMMENCED	YEAR COMPLETED
1	Construction, replacement & repair of flowlines in SPDC swamp	<i>RT/PMI/UT/Borescope</i>	Sunup logistics Limited	<i>SPDC</i>	2022	2022
2	The construction of crude oil & gas lift manifold at Ibigwe field project	<i>Radiographic inspection/MPI</i>	Petra Services	<i>Waltersmith Petrolman Ltd.</i>	2022	2022
3	4" Diebu Creek WH127 Flowline Replacement	<i>Radiographic Inspection / MPI</i>	Miden Systems Ltd	<i>SPDC</i>	2021	2021
4	Material Verification Of 3 Inches SCH.160 X 600 Pounds Weldnet Flange	<i>PMI</i>	Gramen Petroserve Nigeria Limited	<i>SPDC</i>	2021	2021
5	Flowline Replacement Of Nun River WH3s, WH13t & WH16t	<i>PMI / UT / Borescope</i>	Slot Engineering Limited	<i>SPDC</i>	2021	2021
6	4" X-Ray On WH40s Sectional Replacement (Cawthron Channel 3)	<i>Radiographic inspection/MPI</i>	Sajook Nig. Ltd	<i>EROTON</i>	2021	2021
7	Bqrt-3 Flowline Replacement. (Tunu Flowstation)	<i>PMI/UT</i>	Sevoil International Oil And Gas	<i>SPDC</i>	2021	2021
8	Gbaran Produced Water Flowline To Well 7	<i>Radiographic Inspection / MPI / Holiday Detection</i>	Josbani Constructions Nig. Ltd	<i>SPDC</i>	2021	2021
9	Replacement Of Nkali WH5I/5s / WH4I/4s Flowline	<i>Radiographic Inspection / MPI / Holiday Detection</i>	Adland Projects Nig. Ltd	<i>SPDC</i>	2021	2021
10	Provision Of Utilities at Ohaji	<i>Radiographic</i>	Definite Systems	<i>Seplat Petroleum</i>	2021	2021

	South Production Facility	<i>Inspection / MPI</i>	Intl Ltd			
11	NDT on NGP Gas Supply to NGC OB3 Line, Kwale	<i>Radiographic inspection/MPI</i>	Petra Services	<i>Xenergi Limited</i>	2020	2021
12	Gas Gathering Project, Kwale	<i>Radiographic inspection/MPI</i>	Petra Services	<i>Xenergi Limited</i>	2020	2021
13	Flow station Upgrade	<i>Radiographic inspection/MPI</i>	Petra Services	<i>Xenergi Limited</i>	2020	2021
14	Construction of 2.5km x 10" Pipeline Project, Kwale	<i>Radiographic inspection</i>	Petra Services	<i>Xenergi Limited</i>	2020	2021
15	Instrument Gas to Instrument Air Conversion project, Oloma Bonny	<i>Radiographic inspection</i>	Scantex Agencies	<i>Xenergi Limited</i>	2020	2020
16	WH23s Sectional Replacement, Soku	<i>Radiographic inspection/MPI</i>	Kemud International	<i>SPDC</i>	2020	2020
17	Gas Lift Tie-In Project, Jisike	<i>Radiographic inspection/MPI</i>	Seplat Petroleum	<i>SPDC</i>	2020	2020
18	Fire Fighting System Upgrade/Waterline, Ibigwe	<i>Radiographic inspection</i>	Petra Services	<i>Seplat Petroleum</i>	2019	2020
19	Provision of Landing Platform for Gas Well Head, Soku	<i>Radiographic inspection</i>	Scantex Agencies	<i>Watersmith Petrolman</i>	2020	2020
20	Hook up Fabrication & installation	<i>Radiographic inspection/MPI</i>	Wilkriss Nig. Ltd	<i>SPDC</i>	2020	2020
21	Amesl IPP Ariaria Connection Project	<i>Radiographic inspection/MPI</i>	Nibco Engineering Services	<i>SPDC</i>	2019	2020
22	Egbaoma Expansion In-Field Manifold	<i>Radiographic inspection/MPI</i>	Mountain Energy Solution Ltd	<i>SPDC</i>	2020	2020
23	Genesis Gas Connection Project	<i>Radiographic inspection/MPI</i>	Nibco Engineering Services	<i>SPDC</i>	2019	2020
24	WH2L/S Construction Of Tunu cvsb Flowline	<i>Radiographic inspection/MPI</i>	Scantex Agencies	<i>SPDC</i>	2019	2020
25	Export Pump Section Bottlenecking Lift Supply	<i>Radiographic inspection/MPI</i>	Petra Services	<i>Waltersmith Petrolman Ltd.</i>	2019	2020
26	WH15T Flowline Replacement,	<i>Radiographic</i>	Wirelink Services	<i>SPDC</i>	2020	2020

	Opukushi	<i>inspection/MPI</i>				
27	Ibigwe Flowline 8" (5.206km)	<i>Radiographic inspection</i>	Petra Services	<i>Waltersmith Petrolman Ltd.</i>	2018	2019
28	Re-Entry Site Modification Work	<i>Radiographic Inspection / MPI</i>	Chify	<i>SPDC</i>	2019	2019
29	6" Osisioma Gas Pipeline Project (13.1km)	<i>Radiographic inspection</i>	Nibco Engineering Services.	<i>SPDC</i>	2019	2019
30	Replacement of Gas Lift line	<i>Radiographic inspection</i>	Adland	<i>SPDC</i>	2018	2019
31	WH4S Total Replacement, Adibawa	<i>Radiographic inspection</i>	Gamstec Nig. Ltd	<i>SPDC</i>	2019	2019
32	WH33L Flowline Replacement, Otumara	<i>Radiographic inspection</i>	Ikonibo	<i>SPDC</i>	2019	2019
33	4" Cawthron Channel flow line replacement (4.2km)	<i>Radiographic Inspection / MPI</i>	Sajook Nigeria Limited	<i>EROTON</i>	2019	2018
34	Akaso flow line replacement 4"	<i>Radiographic inspection</i>	Sajook Nigeria Limited	<i>EROTON</i>	2018	2018
35	8" Pipeline project Asa- Ibigwe	<i>Radiographic inspection</i>	Petra Services	<i>Waltersmith Petroman Ltd.</i>	2018	2018
36	4" Soku flow line replacement	<i>Radiographic inspection</i>	Scantex Agencies	<i>SPDC</i>	2018	2018
37	Installation of Hook Up Arm	<i>NDT Services</i>	Amban	<i>SPDC</i>	2018	2018
38	Alakiri 4" Flow line replacement	<i>NDT Services</i>	Cakasa Nig Ltd	<i>EROTON</i>	2018	2018
39	4" Sectional replacement Imo River	<i>NDT Services. Instrumentation.</i>	Cakasa Nig Ltd	<i>SPDC</i>	2018	2018
40	Asa-Ibigwe flow station (4.6 km _ 4")	<i>Radiographic inspection</i>	Petra Services	<i>Waltersmith Petroman Ltd.</i>	2018	2018
41	Ibigwe flow station upgrade	<i>Radiographic inspection</i>	Petra Services	<i>Waltersmith Petroman Ltd.</i>	2018	2018
42	4" Awoba/Gbaran flow line replacement	<i>Radiographic inspection</i>	Steve Integrated	<i>SPDC</i>	2018	2018
43	DWNC LACT unit installation	<i>MPI/ Radiographic</i>	Sajook Nigeria	<i>EROTON</i>	2018	2018

		<i>Inspection</i>	Limited			
44	4" Oguta flow line replacement	<i>Radiographic inspection</i>	ELIAS-PAT ENGR.CO.NIG	<i>SPDC</i>	2018	2018
45	4" Orubiri bulk line manifold flow line replacement	<i>Radiographic inspection</i>	Sajook Nigeria Limited	<i>EROTON</i>	2018	2018
46	4" Gbaran construction/ flow line replacement	<i>Radiographic inspection</i>	Romek and Company Limited	<i>SPDC</i>	2018	2018
47	6" X 5.2km Flowline, Soku	<i>MPI/ Radiographic Inspection</i>	Steve Integrated	<i>SPDC</i>	2016	2016
48	6" x 10km Flowline , Asa	<i>Radiographic inspection</i>	Petra Services	<i>Millennium Oil & Gas</i>	2014	2016